

TEST REPORT

Report No. : HL201752004
 Page : 1 of 1
 Date : MAR. 18, 2004

SUPER SHENG ENTERPRISE CO., LTD.
 No. 6, Lane 151, Minsong St., Sanchin Town,
 Taipei Hsien 257, Taiwan, R. O. C.

The following merchandise was submitted and identified by the vendor as:

Type of Product: Bracket
 Style/Item No.: # 1
 Manufacturer/Vendor: SUPER SHENG ENTERPRISE CO., LTD.
 Country of Origin: Taiwan

We have tested the submitted sample(s) as requested and the following results were obtained:

Test Requested: Tensile test

Test Method:

Secure the sample on the tensile machine (INSTRON 5581). Apply an increasing force to the sample until it is old or broken then record the broken load and failure mode.
 (Speed: 5 mm/min.)

Test Results:

Sample	Item load (kgf)	Failure mode
Bracket-# 1	173.32	The bracket was permanent deformation after testing.

Photo Index: Photo "A": Sample picture. (See sample card page 1 of 1)
 Photo "B": Test methods. (See sample card page 1 of 1)
 Photo "C": Failure mode. (See sample card page 1 of 1)

Testing period: Mar. 17, 2004 - Mar. 18, 2004

Signed for and on behalf of
 SGS Taiwan Ltd.

Chen Chang
 Asst. Supervisor



TEST REPORT

Report No.: HL30175B/2004
Page: 1 of 1
Date: MAR. 18, 2004

SUPER SHENG ENTERPRISE CO., LTD.
No. 6, Lane 151, Minsheng St., Sashain Town,
Taipai Hsien 237, Taiwan, R. O. C.

The following merchandise was submitted and identified by the vendor as:

Type of Product: Bracket
Style/Item No.: F 3
Manufacturer/Vendor: SUPER SHENG ENTERPRISE CO., LTD.
Country of Origin: Taiwan

We have tested the submitted sample(s) as requested and the following results were obtained:
TEST REQUIREMENT:

Tensile test

Test Method:

Secure the sample on the tensile machine (INSTRON 5581). Apply an increasing force to the sample until it is stiff or broken then record the broken load and failure mode.
(Speed: 5 mm/min.)

Test Results:

Sample	Max. load (kgf)	Failure mode
Bracket-F 3	116.27	The bracket was permanent deformation after testing.

Photo Index: Photo "A": Sample picture. (See sample card page 1 of 1)
Photo "B": Test methods. (See sample card page 1 of 1)
Photo "C": Failure mode. (See sample card page 1 of 1)

Testing period: Mar. 17, 2004 ~ Mar. 18, 2004

Signed for and on behalf of
SGS Taiwan Ltd.


Owen Cheng
Asst. Supervisor

The test report is valid only if the sample is tested in the laboratory of SGS Taiwan Ltd. and the test results are reported in the test report. The test report is valid only if the sample is tested in the laboratory of SGS Taiwan Ltd. and the test results are reported in the test report. The test report is valid only if the sample is tested in the laboratory of SGS Taiwan Ltd. and the test results are reported in the test report.

SGS Taiwan Ltd. | No. 25, Wu Ding Road, Waka Industrial Zone, Neihu District, Taipei / 台北市內湖區吳定路25號
TEL: (886) 2 2707 8888 | FAX: (886) 2 2707 8889 | WWW: www.sgs.com.tw

1000