

TEST REPORT

Report No. : HL30475P/2004
Page : 1 of 1
Date : MAR. 18, 2004

SUPER SHENG ENTERPRISE CO., LTD.
No. 6, Lane 151, Minsong St., Sanhsia Town,
Taipi Hsien 237, Taiwan, R. O. C.

The following merchandise was submitted and identified by the vendor as:

Type of Product: Bracket
Style/Item No.: # 7
Manufacturer/Vendor: SUPER SHENG ENTERPRISE CO., LTD.
Country of Origin: Taiwan

We have tested the submitted sample(s) as requested and the following results were obtained:

Test Requested:

Tensile test

Test Method:

Secure the sample on the tensile machine (INSTRON 5581). Apply an increasing force to the sample until it is slid or broken then record the broken load and failure mode.

(Speed: 5 mm/min.)

Test Results:

Sample	Max. load (kgf)	Failure mode
Bracket-# 7	109.12	The bracket was permanent deformation after testing.

Photo Index: Photo "A": Sample picture. (See sample card page 1 of 1)
Photo "B": Test methods. (See sample card page 1 of 1)
Photo "C": Failure mode. (See sample card page 1 of 1)

Testing period: Mar. 17, 2004 – Mar. 18, 2004

Signed for and on behalf of
SGS Taiwan Ltd.



Owen Cheng
Asst. Supervisor

THE RESULTS REPORTED ON THIS REPORT, SUBJECT TO THESE CONDITIONS OF SERVICE, ARE VALID ONLY FOR THE PURPOSES AND CONDITIONS SPECIFICALLY IDENTIFIED ON THE REPORT. THE RESULTS REPORTED ON THIS REPORT ARE VALID ONLY FOR THE PURPOSES AND CONDITIONS SPECIFICALLY IDENTIFIED ON THE REPORT. THE RESULTS REPORTED ON THIS REPORT ARE VALID ONLY FOR THE PURPOSES AND CONDITIONS SPECIFICALLY IDENTIFIED ON THE REPORT. THE RESULTS REPORTED ON THIS REPORT ARE VALID ONLY FOR THE PURPOSES AND CONDITIONS SPECIFICALLY IDENTIFIED ON THE REPORT.

TW-0870188

TEST REPORT

Report No. : HL30175G/2004

Page : 1 of 1

Date : MAR 18, 2004

SUPER SHENG ENTERPRISE CO., LTD.
No. 6, Lane 151, Minsheng St., Sankua Town,
Tapei Hsien 237, Taiwan, R. O. C.

The following merchandise was submitted and identified by the vendor as:

Type of Product: Bracket
Style/Item No.: # E
Manufacturer/Vendor: SUPER SHENG ENTERPRISE CO., LTD.
Country of Origin: Taiwan

We have tested the submitted sample(s) as requested and the following results were obtained:

Test Requested:

Tensile test

Test Method:

Secure the sample on the tensile machine (INSTRON 5501). Apply an increasing force to the sample until it is stiff or broken then record the broken load and failure mode.

(Speed: 5 mm/min.)

Test Results:

Sample	Max. load (kgf)	Failure mode
Bracket-# E	152.98	The ball stud was separated from the bracket.

Photo Index:

Photo "A": Sample picture. (See sample card page 1 of 1)

Photo "B": Test methods. (See sample card page 1 of 1)

Photo "C": Failure mode. (See sample card page 1 of 1)

Testing period:

Mar. 17, 2004 - Mar. 18, 2004

Signed for and on behalf of
SGS Taiwan Ltd.


Owen Cheng
Asst. Supervisor

This Test Report is issued by the Company, subject to the General Conditions of Service annexed hereto. All rights are reserved. No part of this report may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, without the prior written permission of the Company. All rights reserved. TW 067015G

TW 067015G

TEST REPORT

Report No. : HL30175H/2004

Page : 1 of 1

Date : MAR. 18, 2004

SUPER SHENG ENTERPRISE CO., LTD.
No. 6, Lane 171, Minsheng St., Xuehsia Town,
Taipei Hsien 237, Taiwan, R. O. C.

The following merchandise was submitted and identified by the vendor as:

Type of Product: Bracket
Style/Item No.: F 09A
Manufacturer/Vendor: SUPER SHENG ENTERPRISE CO., LTD.
Country of Origin: Taiwan

We have tested the submitted sample(s) as requested and the following results were obtained:
test Requested:

Tensile test

Test Method:

Secure the sample on the tensile machine (INSTRON 5581). Apply an increasing force to the sample until it is old or broken then record the broken load and failure mode.

(Speed: 3 mm/min.)

Test Results:

Sample	Max. load (kgf)	Failure mode
Bracket-F 09A	180.92	The ball stud was separated from the bracket.

Photo Index: Photo "A": Sample picture. (See sample card page 1 of 1)

Photo "D": Test methods. (See sample card page 1 of 1)

Photo "C": Failure mode. (See sample card page 1 of 1)

Testing period: Mar. 17, 2004 – Mar. 18, 2004

Signed for and on behalf of
SGS Taiwan Ltd.


Owen Cheng
Asst. Supervisor

This Test Report issued by the Company is valid only when signed and stamped by the authorized personnel. It is not valid if the signature and stamp are missing. The Company is not responsible for the accuracy of the test results if the sample is not properly prepared or if the test method is not followed. The Company is not responsible for the accuracy of the test results if the sample is not properly prepared or if the test method is not followed. The Company is not responsible for the accuracy of the test results if the sample is not properly prepared or if the test method is not followed.

TW 0870180